

REPORT OF THOROUGH EXAMINATION

This report complies with the requirements of the Lifting Operations and Lifting Equipment Regulations 1998 and Power Regulations 1998

Date of Thorough Examination: 15/01/2024		Date of Report: 15/01/2024		Report number: 6M240047	
Name and Address of employer for whom the thorough examination was made: M J Hickey Plant, Unit 11 SBC Bristol Way, Slough, SL1 3TD			Address of premises at which the examination was made: GallifordTry Infrastructure, Hampworth Road, Landford, Salisbury, SP5		
Description and identification of the equipment: Quick Hitch Type: Hill Tefra Quick Hitch Quick Hitch S/N: Illegible Equipment Type: Hitachi ZX135US-6 Excavator ID: HCMDAS50A00102329			Safe Working Load(s): In Accordance with manufacture specification.	Date of manufacture if known: Unknown	Date of last thorough examination: 16/01/2023
Is this the first examination after installation or assembly at a new site or location?			Was the examination carried out:		
YES ☒ NO ☐			Within an interval of 6 months? YES ☐ NO ☒		
If the answer to the above question is YES has the equipment been installed correctly?			Within an interval of 12 months? YES ☐ NO ☒		
YES ☒ NO ☐			In accordance with an examination scheme? YES ☒ NO ☐		
			After the occurrence of exceptional circumstances? YES ☐ NO ☒		
Identification of any part found to have a defect which is or could become a danger to persons and a description of the defect: (If none state NONE) None Found.					
Is the above an existing or imminent danger to persons *Note-This is a reportable defect				YES ☐	NO ☒
Is the above a defect which is not yet but could become a danger to persons: (If YES state the date by when) N/A				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above: Equipment was found to be in safe working order at time of inspection.					
Particulars of any tests carried out as part of the examination: (If none state NONE) None.					

Observations / additional comments relative to this thorough examination:

Equipment was found to be in safe working order at time of inspection.

IS THIS EQUIPMENT SAFE TO OPERATE?			YES ☐	☒	NO ☐
Name & Qualifications of person making this report: James Walsh City & Guilds, CITB		Name of person signing or authenticating this report on behalf of the author: Signature: <i>Mr James Walsh</i>		Latest date by which next thorough examination must be carried out: 14/07/2024	
Name and address of employer of persons making and authenticating this report: Walsh Plant Ltd, Unit 3 Birchwood Industrial Estate, Hoe Lane, Nazeing, EN9 2RJ					